



department of water, air and waste management

RECORD COPY  
File Name CHAMBERLAIN MFG CO HAZWASTE FACIL  
Senders Initials REC CLINTON

November 21, 1983

To: GENE EVANS  
FOR INFO & FILE  
REC  
11/28/83

Mr. Dave Crawford  
Waste Management Branch  
US EPA Region VII  
324 East 11th Street  
Kansas City, Missouri 64106

RE: Collis Division of Chamberlain Manufacturing, Clinton, Iowa

Dear Mr. Crawford:

My staff has reviewed the Phase I report developed by Terracon Consultants, Inc. for Collis Division.

It appears that the provisions of the 3013 Admin Order, Phase I have been satisfied. Surficial and groundwater contamination has been identified. However, the extent of contamination has not been determined on the ground surface, in the unconsolidated sediments or in the bedrock. The primary conclusion that can be drawn from this report is that considerable contamination exists in the area and a much more extensive investigation is required to determine extent and remedial measures to be taken.

Any remedial actions to be taken by Collis should be in conjunction with the Phase II study of their situation. Before any cleanup occurs, it is imperative that the extent of contamination be determined as accurately as possible.

If you should have any questions concerning these matters, please advise.

Sincerely,

FIELD SERVICES DIVISION

Keith Bridson, P.E.  
Chief, Central Assistance Branch

cc: Pete Hamlin  
Rod Vlieger  
✓ Bob Campbell



R00312967  
RCRA RECORDS CENTER

KB:PAL:pmk/FS/W322Z01.01